

Work Order ID 130394

130394

Page 1

Friday, March 13, 2015 10:29:35 AM

Item ID: D3136-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Window Assembly
Start Date: 3/10/2015 Start Qty: 2.00 ***2*** Cust Item ID:
Required Date: 3/11/2015 Req'd Qty: 2.00 ***2*** Customer: CSTER01
Reference: RMA RA111978

Approvals: Process Plan: mf Date: 15-3-13 Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3136	F

100 0.00

100

QC

Quality Control

Memo

INSPECT RA 111978
D3136-041 X 2 BXXX

PARTS WERE SCRAPPED AT CUSTOMER'S FACILITY

mf 15-3-13

110 QC21- Final Inspection - Work Order Release 0.00

110

QC

Quality Control

Memo

0.00

mf 15-3-13

Picklist Print

Page 1

Friday, March 13, 2015 10:29:34 AM

Work Order ID: 130394

130394

Parent Item: D3136-041

D3136-041

Parent Item Name: Window Assembly

Start Date: 3/10/2015

Required Date: 3/11/2015

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP B04.02.04ReformatKJ/DS

IPP C Thermoform in house 05/07/2007 DL

IPP D Rev E 07.09.28 EC verified by: DD

IPP Rev E

14/01/20 Repace "Folio" with Work Instruction. DL

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3136-041		Manufactured	No				Each	14.0000		2			

D3136-041

Window Assembly

Location

Loc Qty

Loc Code

ST435

14

120086

1

121385

2

128359

4

54571

1

64892

1

66826

3

74430

2

2x XXX
MF
15-3-13